ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ, ਉਸਾਰੀ ਉਪ ਮੰਡਲ ਨੰ.2 ਭ ਤੇ ਮ ਸ਼ਾਖਾ, ਸੰਗਰੂਰ।

ਵੱਲ

ਪ੍ਰਿੰਸੀਪਲ, ਸ਼੍ਰੀ ਸੂਰਜਕੁੰਡ ਸਰਵਹਿੱਤਕਾਰੀ ਵਿੱਦਿਆ ਮੰਦਿਰ, ਸੀਨੀਅਰ ਸੈਕੰਡਰੀ ਇੰਗਲਿਸ਼ ਮੀਡੀਅਮ ਸਕੂਲ, ਖਡਿਆਲ ਰੋਡ, ਸੁਨਾਮ (ਸੰਗਰੂਰ)।

ਨੰਬਰ: 1281

ਮਿਤੀ:

14/5/2024

ਵਿਸਾ:-

ਸਾਲ 2024-25 ਦੇ ਲਈ ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਜਾਰੀ ਕਰਨ ਸਬੰਧੀ।

ਉਪਰੋਕਤ ਵਿਸ਼ੇ ਸਬੰਧੀ ਪ੍ਰਾਪਤ ਹੋਇਆ ਕੇਸ ਸਬੰਧਿਤ ਜੇ.ਈ. ਵੱਲੋਂ ਲੋੜੀਂਦੀ ਇੰਨਸਪੈਕਸ਼ਨ ਕਰਨ ਉਪਰੰਤ ਸਮੇਤ ਸਰਟੀਫਿਕੇਟ ਆਪ ਜੀ ਨੂੰ ਅਗਲੇਰੀ ਯੋਗ ਕਾਰਵਾਈ ਹਿੱਤ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ। ਲੋੜੀਂਦੀ ਇੰਨਸਪੈਕਸ਼ਨ ਫੀਸ ਬਾਬਤ ਰੁਪਏ 10000/- (ਦਸ ਹਜ਼ਾਰ ਰੁਪਏ ਸਿਰਫ) ਜੀ.ਆਰ. ਨੰ: 664999 ਮਿਤੀ: 14/05/2024 ਰਾਹੀਂ ਜਮਾਂ ਕਰਵਾ ਲਈ ਗਈ ਹੈ।

ਨੱਥੀ:- ਸਰਟੀਫਿਕੈਟ

ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ, ਉਸਾਰੀ ਉਪ ਮੰਡਲ ਨੇ.2 ਭ ਤੇ ਮ ਸ਼ਾਖਾ, ਸੰਗਰੂਰ

ਪਿੱਠ ਅੰਕਣ ਨੰ.

ਮਿਤੀ:

ਉਪਰੋਕਤ ਦਾ ਉਤਾਰਾ ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ, ਪ੍ਰਾਂਤਕ ਮੰਡਲ ਭ ਤੇ ਮ ਸ਼ਾਖਾ ਸੰਗਰੂਰ ਨੂੰ ਸੂਚਨਾਂ ਹਿੱਤ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ ਜੀ।

> ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ, ਉਸਾਰੀ ਉਪ ਮੰਡਲ ਨੰ.2 ਭ ਤੇ ਮ ਸ਼ਾਖਾ, ਸੰਗਰੂਰ।

-Part-II

Building Safety Report

Name of School:

Shri Surajkund Sarvhitkari Vidya Mandir, Sen. Sec. English Medium School, Sunam.

I have visited the above-mentioned School Building along with Sh. Satnam Singh (Junior Engineer) and on visually inspection; it seems visually safe subject to the following observation & conditions.

- a) Parameters to check the stability and safety of building as Architectural Drawings, Bearing capacity, Foundation detail, Structural Drawings, Technical Specifications, Test Reports of Material used, Quality Control reports and certificate from the Engineer in-Charge for construction are not available.
- b) In case any addition, alteration or expansion and modification to this building are done certificate may be obtained after the completion from the undersigned.
- c) In case the building is affected by flood or if there is any settlement of walls/ foundation or sagging of roofs etc. immediate inspection of the undersigned be arranged to check stability and safety of the building.
- d) This Certificate holds validity only with valid Fire Safety Certificate. A separate certificate regarding Fire Fighting should be obtained from the competent Authority.
- e) A separate certificate regarding Electrical works should be obtained from the competent Authority.
- f) The owner of the building / Management is fully responsible regarding safety of the building from all angles in spite of the report.
- g) The covered area of the building is <u>As per Drawings Sft</u>.
- The report is not valid for legal purpose.
- The building visually seems safe to occupy for normal use to One Year, upto 31-03-2025

AJE.

Sub Divisional Engineer

Const. \$ub Divn.No.2 PWD, B&R

Sangrur